

WEAR PARTS





EHWA DIAMOND





PCD, PCBN, TUNGSTEN CARBIDES, CERAMICS

WEAR PARTS

Longer tool life thanks to excellent wear resistance Customized solutions for all applications

APPLICATIONS

- Centerless grinding machines
- Cylindrical grinding machines
- Measuring probes
- Bearing manufacturing
- Various machines







Centerless blades for centerless grinding










Sliding shoes & V-blocks work-rest parts



Backing plates for bearing manufacturing



Gauges measuring probes





Friction can be minimized by polishing PCD surface to a minimum Ra value of 0.02.



Ceramic exhibits exceptional chemical resistance, effectively preventing chemical wear and surface scratches on the workpieces